

TABLE OF CONTENTS

	Page
FOREWORD	1
Units	1
1. SCOPE	3
2. INTRODUCTION	5
2.1 Damage Mechanisms	5
2.2 Process Conditions	5
2.3 Materials Factors	5
2.4 Welding and Post-Weld Heat Treatment (PWHT)	6
2.5 Classification of Risk	6
2.6 In-Service Inspection	6
3. PROCESS CONDITIONS	7
3.1 Conditions for SSC	7
3.2 Conditions for HIC	8
4. ASSESSMENT OF RISK	11
4.1 Probability of Wet H ₂ S Attack	11
4.2 Consequences of Wet H ₂ S Attack	12
4.3 Risk Assessment	13
4.4 Re-Evaluation of Risk	13
5. NEW CONSTRUCTION	15
5.1 General Materials Requirements	15
5.1.1 Established Requirements for Sour Service	15
5.1.2 Improvements in Materials	15
5.1.3 Different Product Forms	15
5.1.4 Microstructural Homogeneity	16
5.1.5 Material Test Reports	16
5.2 Plate for Improved Resistance to HIC	16
5.2.1 General	16
5.2.2 Material Production	16
5.2.3 Chemical Composition	17
5.2.4 Ultrasonic Examination	18
5.2.5 HIC Testing	18
5.2.6 HIC Acceptance Limits	18
5.3 Design	18
5.4 Welding	19
5.4.1 General	19
5.4.2 Post Weld Heat Treatment (PWHT)	20
5.5 Welding Procedure Qualification (WPQ)	20
5.5.1 Steels for Qualification	20
5.5.2 Hardness Testing	20
5.5.3 Welding Variables	20
5.6 Production Welding	21
5.6.1 Welding Procedure Variables	21

5.6.2	Production Hardness Tests	21
5.6.3	Production Test Plates	21
5.6.4	Non-Destructive Examination of Welds	22
6.	WELDING OF IN-SERVICE EQUIPMENT	23
6.1	General	23
6.2	Damage Caused by Prior Service	23
6.3	Hydrogen Activity	23
6.4	Hydrogen Removal	24
6.4.1	General Requirements	24
6.4.2	Heat Treatment Details	24
6.5	Testing and Inspection after Welding	25
7.	INSPECTION OF IN-SERVICE EQUIPMENT	27
7.1	General	27
7.2	Establishment and Review of Inspection Frequency and Extent	27
7.3	Inspection methods	28
7.3.1	Visual	28
7.3.2	WFMPI	28
7.3.2.1	Surface Preparation	29
7.3.2.2	Technique	29
7.3.3	Ultrasonic Testing	30
7.3.3.1	Detection and Sizing	30
7.3.3.2	UT Attenuation	31
FIGURES		33
Fig. 1	Typical Forms of Wet H ₂ S Damage	33
Fig. 2	Vickers Hardness Testing for Welding Procedure Qualification	34
Fig. 3	Examples of Blistering	35
Fig. 4	Trans-weld and HAZ Cracking	36
Fig. 5	Cracking in HAZ and Parent Materials	37
Fig. 6	Stepwise Cracking Induced by Welding Stresses	38
LIST OF ABBREVIATIONS		39
LIST OF REFERENCED DOCUMENTS		41
EEMUA PUBLICATIONS — SUMMARY LIST		43