

Contents

Preface	VI
Acknowledgements.....	VI
Abbreviations/Acronyms used in this Guide	VII
1 Introduction.....	1
1.1 Purpose	2
1.2 Scope.....	2
1.2.1 Note on Carbon 0.5Mo Steels.....	2
1.3 Joint Industry Projects.....	2
2 General Considerations	3
2.1 Time Dependency.....	3
2.2 Damage Development.....	3
2.3 Management Options.....	4
2.4 Damage Detection	5
3 Specific Considerations.....	7
3.1 Identifying Carbon Steel Equipment and Systems Welded Without PWHT	7
3.1.1 Important Aspects to Consider.....	7
3.2 Accounting for Operating Conditions, Temperature/Pressure Excursions, etc., Including Periods Before Computerised Data Logging	7
3.2.1 Important Aspects to Consider.....	8
3.2.2 Possible Future Outcomes.....	9
3.3 Plant Operating Hours	9
3.3.1 Important Aspects to Consider.....	9
3.4 Issues Associated with Using Reduced Hydrogen Partial Pressure or Reduced Temperature for Assessment of Internally Lined Vessels	10
3.4.1 Linings for Corrosion Protection	10
3.4.2 Linings for Temperature Protection	10
3.4.3 Important Aspects to Consider.....	11
3.5 Plant in Anacortes Arrangement/with Similar Characteristics.....	12
3.5.1 Important Aspects to Consider.....	12
3.6 Dedicated Monitoring and IOWs, Reporting of Exceedances.....	12
3.6.1 Important Aspects to Consider.....	12

3.7 Awareness of Appropriate NDE Techniques and Engagement with Suppliers	13
3.7.1 Traditional Techniques	13
3.7.2 Modern Advanced Techniques.....	13
3.7.3 Important Aspects to Consider.....	14
3.7.4 Possible Future Outcomes.....	14
3.8 What to Inspect and Preparation of Equipment for Inspection.....	15
3.8.1 Preparation for Inspection	15
3.8.2 Important Aspects to Consider	15
3.9 Application of NDE (Including Validation and Certification).....	16
3.9.1 Important Aspects to Consider	16
3.9.2 Possible Future Outcomes:	17
3.10 Inspection Levels – How Much to Inspect (Scale/Extent/Amount)	17
3.10.1 Important Aspects to Consider	18
3.11 Limitations to Weld Inspections Associated With Fittings.....	18
3.11.1 Important Aspects to Consider	19
3.12 Assessment of Hydrogen Partial Pressure in Liquid Packed Lines	19
3.12.1 Important Aspects to Consider	20
References	21